	Туре	L#	Hits	Search T xt	DB	Tim Stamp	C mm n ts	
1	BRS	L1	95210 9	Cu r copper r Cu-all y r copper-alloy or Cu-line or copper-line or Cu-interconnect\$4 or copper-interconnect\$4	1 _	2003/06/04 14:07		
4	BRS	L16	1424	1 same (slot or cut or split or open\$4) same (stress or strain or stress-relief or strain-relief)	i	2003/06/04 14:35		
5	BRS	L23	396	16 and semiconductor	USPA T; US-PG PUB; EPO; JPO; DERW ENT; IBM_T DB	2003/06/04 14:37		

	Туре	L#	Hits	Search T xt	DB	Tim Stamp	Comm n
1	BRS	L1	95210 9	Cu r pp r r Cu-alloy r copper-alloy or Cu-line or copper-line or Cu-interconnect\$4 or copper-interconnect\$4	USPA T; US-PG PUB; EPO; JPO; DERW ENT; IBM_T DB	2003/06/04 14:07	
3	BRS	L9	112		EPO;	2003/06/04 14:12	